Coping process for CD-ROM of bundled software may not read on macOS Sierra（Version 10.12）

CD-ROM of bundled software may not read on macOS Sierra (Version 10.12)
In this case, install the software by following procedure.

1. Start up Mac/Macintosh and insert CD-ROM to CD-ROM drive.
2. Start up Disk Utility (Applications→Utilities →Disk Utility)

3. Select volume label of CD-ROM and execute [Image from "(volume label)"]


4. Put any name and save the image on Desktop by save dialogue.

5. Input User name and Password.

6. Create image of CD-ROM and display image file icon on the Desktop.

7. Double click icon that is created step 6. and read desk image.

CD-ROM icon will be displayed. The same as reading CD-ROM.

8. The same as usual CD-ROM、execute Software Installer and execute installer from install menu application.

Finish install procedure.